

## EXCITING NEWS:

*Accutome clinical and ultrasound products are now part of Keeler.*

[www.keelerusa.com](http://www.keelerusa.com) | [www.accutome.com](http://www.accutome.com)

3222 Phoenixville Pike, Bldg 50 | Malvern, PA 19355 USA | [customerservice@keelerusa.com](mailto:customerservice@keelerusa.com)  
800.523.5620 | 610.353.4350 | F: 610.353.7814

November 27<sup>th</sup>, 2019

With the release of Accutome Connect version 8.03.01, Keeler is updating the Minimum PC Recommended Specifications:

- Operating System:** Window7, or 10 (Windows 10 64-bit is recommended)
- CPU:** CPU Intel Core i3 minimum (Core i5 recommended)
- Screen resolution:** (1280X1024 – 1920X1200)
- RAM:** 4GB+
- Storage:** 100GB+ HDD

Validation of this new release was performed on the following brands of laptops (with the 8<sup>th</sup> edition CPU):

- Microsoft Surface
- Asus Vivobook
- Acer Aspire 5 and newer

To download the Accutome Connect version 8.03.01, please visit the below link to access the updated software.

- <https://www.keelerusa.com/a-scan-plus-connect>
- <https://www.keelerusa.com/b-scan-plus>
- <https://www.keelerusa.com/ubm-plus>

For help with this upgrade please contact Keeler's Diagnostic Product team at 610.353.4350